Meage Gile m/037/088

## **Inspection Report**

Case File:

UTU-72499/SUMMO

**Inspector:** 

Denice Swanke, Physical Scientist

Date of Inspections: 11 February 2004 **Date of Report:** 

12 February 2004

RECEIVED

FEB 18 2004


DIV. OF OIL, GAS & MINING


I received a phone call from Chuck Bower on 10 February indicating that the drillers were going to start working on BLM land on the 11th. I went out to the site, met with Chuck and observed the drilling operation for about one hour. There were several mechanical problems being trouble shot, and I finally left the site without seeing a core. The work was occurring at site 12, where Chuck expects to drill to a depth of 600'. I took 2 photos, which are attached, as is a GIS map of the drill site relative to the proposed line as GPS'd in October.

The drilling crew is working a schedule of 8 days on/6 days off, and will resume work on 18 February. I do not expect that a hole will be completed on BLM until the 20th. I plan to complete another inspection the week of 23 February and will mail a copy of this report to Paul Baker, UDOGM.


re: M0370088

## SUMMO drilling project as of 11 February 2004










dull riga site 12 view to NW from Lisbon Valley road



drill rig @ Ste 12 view to s-sE